

## **Study into the effects of radiation exposure on seismic integrity claims for a neutron detector**

Dissertation submitted to The University of Liverpool for the degree of Master of Science in Nuclear Science & Technology in the Faculty of Engineering and Physical Sciences

**2014**  
**Mathew Flusk**

### **ABSTRACT**

In order to assess without experiment whether a gas-filled neutron detector could continue to adhere to seismic qualification standards after suffering irradiation, mechanisms of damage were identified and compared to operating conditions. Operating conditions were given as 333-353 K temperature,  $2 \times 10^8 \text{ cm}^{-2} \text{ s}^{-1}$  fast flux ( $1.6 \times 10^{17} \text{ cm}^{-2}$  fluence) and  $8 \times 10^9 \text{ cm}^{-2} \text{ s}^{-1}$  thermal flux ( $6.3 \times 10^{18} \text{ cm}^{-2}$  fluence) equivalent to  $2.5 \times 10^{-5}$  displacements per atom (dpa). Appropriate seismic standards were suggested and the testing methods described. The major structural materials in the IN35D detector, aluminium, stainless steel and alumina ceramic, were characterised and alloy compositions produced. Radiation induced damage mechanisms were described for both thermal and fast flux and the particular mechanisms for each structural material identified. Peer-reviewed literature was consulted to predict the effect of radiation damage for a given fluence on mechanical properties relevant to seismic integrity such as yield stress, ultimate tensile stress, elongation and ductility. For aluminium, fluences of below  $10^{21} \text{ cm}^{-2}$  produced no noticeable changes in mechanical properties. Between  $10^{21}$  and  $10^{22}$  damage may occur if temperature is high enough. Above  $10^{22}$  flux significant damage and changes in aluminium mechanical properties occurs. For stainless steel, a comparison to dpa was required and it was found that neutron damage below  $1 \times 10^{-3}$  dpa produce no noticeable effects. Finally, for alumina, a neutron fluence below  $10^{21} \text{ cm}^{-2}$  had no effect on mechanical properties. It was therefore decided that the minimum neutron fluence to produce noticeable changes in mechanical properties is, in all cases, at least an order of magnitude greater than the operating conditions for the detector, and even then an increase in temperature would be required to produce significant changes in ductility and fracture toughness to affect the ability of the device to adhere to seismic standards.

The preparation of this report was possible through Corporate Risk Associate's ongoing support for post-graduate research undertaken throughout a number of outstanding universities.

